

STAY AWAY FROM MACHINERY

STOP

THINK

DO

If you are not using machinery, stay away.

- Machinery includes all vehicles, plant, and equipment.
- Stay at least 30 metres away from operating machinery when not using/repairing it. This is the exclusion zone.
- Stay at least 3 metres away from operating machinery when you're assisting the operator.
- Stay at least 5 metres away from powerlines or pressurised water pipes.
- If you want to speak to the operator of the machine, make eye contact and wait for the operator to stop before approaching.
- When machinery is being serviced, maintained, or repaired, the lock out procedure must be followed.